ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
1

Ward Name
Kempegowda Ward

Street ID
W0522, W0461, W0459, W0463, W0437, W0453, W0465, W

Street Name
NA, Shetty Lyt, 2nd Main Rd, Shetty Lyt, 1st Main Rd, 6th Crs, Shetty Lyt, 4th Main Rd

Significant Landmark
Surabhi lauout 2nd main and cross road

Segment No.
1/C-W0522/S110713

Total Length (m)
293.41

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	181.17	77.599257	13.092559	77.600923	13.092673	M0013	DEAD END
2	79.52	77.599442	13.093199	77.599464	13.093917	W0518	W0435
3	32.72	77.600419	13.092658	77.600400	13.092953	W0522	W0518

Work Details

History of Road / Lane / Circles

Name of the Work
Asphalting and Improvements to Roads at Surabhi lauout 2nd main and cross road in Ward no 01 of Yelahanka Sub-Division Yelahanka zone

Sanctioned Estimated Amount (Rs.)
4500000

Sanctioned Year
2017

Year
2017 - 2018

Type of Work
Asphalting

Other Work Type

Tender
Not a Tender

Work Details
Asphalting and Improvements to Roads at Surabhi lauout 2nd main and cross road in Ward no 01 of Yelahanka Sub-Division Yelahanka zone

Job No. / Work Code
001-17-000036

Work Order No.
BBMP/EE (YNK.D)/WO/152/2017 -18

Work Order Date
31/03/2017

Period of Extention
90 DAYS

Defect Liability Period From
30/04/2017

Defect Liability Period To
29/04/2018

Multiple road involved with the same Job No/ Work Code #
Yes

Contractor Details

Name of Contractor
KRIDL

Contractor Reg No (BBMP/PWD)

Expenditure Booked \ Released (Rs)
0.00

Phone No.

E-Mail ID

9449863065

Field Inspection Details

Number of Trees	Any Other Information	Name
12		SACHIN
Date of Inspection	**Remarks**	
25/05/2017	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 1 **Ward Name:** Kempegowda Ward **Street ID:** VA522, VA451, VA459, VA453,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	25/05/2017	24/06/2017	COMPLETED
SE	VASU K M	25/05/2017	24/06/2017	COMPLETED
EE	VASU K M	25/05/2017	24/06/2017	COMPLETED
AEE	DEVARAJ	25/05/2017	24/06/2017	COMPLETED
AE	SACHIN	25/05/2017	24/06/2017	COMPLETED
AE	SACHIN	25/05/2017	24/06/2017	COMPLETED

Asst. Executive Engineer
Yelahanka Sub. Divison
(BBMP Ynk. Zn)
Yelahanka, Bangalore

Zone: YELAHANKA **Ward No:** 1 **Ward Name:** Kempegowda Ward **Street ID:** W0522, W0461, W0459, W0463,